



G. Trenholm Walker
Thomas P. Gressette, Jr.
Ian W. Freeman
John P. Linton, Jr.
Charles P. Summerall, IV

THOMAS P. GRESSETTE, JR.
Direct: 843.727.2249
Email: Gressette@WGFLAW.com

December 26, 2018

Via Email Only

Newman Jackson Smith, Esquire
Nelson Mullins

Andrew Bateman, Esquire
Jeffrey M. Nelson, Esquire
Office of Regulatory Staff

RE: Daufuskie Island Utility Company, Inc.
Docket No. 2018-364-WS
46 & 36 Driftwood Cottage Lane (Halwig and Noller Residences)

Dear Counselors:

In response to the correspondence from ORS dated December 21, 2018, and pursuant to requests by the Customers (Halwig and Noller), service has been activated at the 46 & 36 Driftwood Cottage Lane.

However, it is my understanding that certain equipment on one or both of the Customers' properties (customer side of the meters) has been damaged by tides and/or erosion and that repairs are necessary and/or underway. The damaged items were installed only a few months ago, which highlights the reasons providing service to these homes is ill advised and risky. DIUC will cooperate as it is able, but I would note that it is the Customers' responsibility to comply with all permitting and inspection requirements for repairs conducted on their properties.

I have not visited the sites this week, so I am not certain of the issues. I do hope for the Customers' that these matters can be easily remedied.

Sincerely yours,

/s/
Thomas P. Gressette, Jr.